


If necessary, try resetting the printer by putting a paper clip in the underneath of the printer as per the picture below



Or you can re calibrate by pressing down the X and the pause button together this usually spits out about 4/5 labels.

